



**ECR** international  
EST. 1928  
A Family of Heating & Cooling Brands.

# Technical Bulletin

2201 Dwyer Ave. • P.O. Box 4729 • Utica, NY 13504-4729 • Ph: 315-797-1310 • Fax: 315-797-3762 • E-Mail: info@ecrinternational.com • Web: www.ecrinternational.com

**BULLETIN NO. 20210902TS**

**DATE:** 9/2/2021

**PRODUCT:** All

**FROM:** Technical Service Department

**TITLE:** Flooded HVAC Equipment.

**IN THE INTEREST OF PUBLIC SAFETY, ECR INTERNATIONAL, INC. SUPPORTS WARNINGS ISSUED BY THE AIR CONDITIONING, HEATING AND REFRIGERATION INSTITUTE (AHRI) THAT RECOMMENDS THE REPLACEMENT OF ALL FLOOD DAMAGED HVAC EQUIPMENT REGARDLESS OF ITS AGE.**

**Replacing only the operating controls of flood damaged HVAC equipment may not be sufficient if other parts of the equipment like piping, venting, burners, insulation, etc., have been affected by flood waters.**

**IT IS ALWAYS SAFER TO REPLACE RATHER THAN REPAIR.**